


### **APPENDIX 3: Photographs of test setup**

#### **Radiated Spurious Emission**


**Front**




**Rear (Below 30 MHz)**



**Rear (Below 1 GHz)**



**Rear (Above 1 GHz)**




### Pre-check of Worst Case Position

**EUT  
X-axis**



**Cable (antenna)  
X-axis**



**Y-axis**



**Y-axis**



**Z-axis**



**Z-axis**




### Frequency Stability



**Photo 1**

\* During the test, the door of the temperature and humidity chamber was closed.



**Photo 2**

**End of Report**