

Philips Consumer Electronics
EMC Competence Centre
Building SFH-p 015
Eindhoven, The Netherlands

EMC TEST REPORT

Rep.No: AR6-877150

PHOTO OF MEASURING SET-UP


Equipment Under Test:

DB102

Serial Number:

EUT72

VIEW OF MEASURING SET-UP: Mains Disturbances; View at cables



EMC TEST REPORT

Rep.No: AR6-877150

PHOTO OF MEASURING SET-UP

Equipment Under Test:


DB102

Serial Number:

EUT72

VIEW OF MEASURING SET-UP: Radiated Disturbances

OVERVIEW



Philips Consumer Electronics
EMC Competence Centre
Building SFH-p 015
Eindhoven, The Netherlands

EMC TEST REPORT

Rep.No: AR6-877150

PHOTO OF MEASURING SET-UP

Equipment Under Test:


DB102

Serial Number:

EUT72

VIEW OF MEASURING SET-UP: Radiated Disturbances

VIEW AT CABLE ROUTING



Philips Consumer Electronics
EMC Competence Centre
Building SFH-p 015
Eindhoven, The Netherlands

EMC TEST REPORT

Rep.No: AR6-877150

PHOTO OF MEASURING SET-UP

Equipment Under Test:


DB102

Serial Number:

EUT72

VIEW OF MEASURING SET-UP: Radiated Disturbances

VIEW AT FRONT



Philips Consumer Electronics
EMC Competence Centre
Building SFH-p 015
Eindhoven, The Netherlands

EMC TEST REPORT

Rep.No: AR6-877150

PHOTO OF MEASURING SET-UP

Equipment Under Test:

DB102

Serial Number:

EUT72

VIEW OF MEASURING SET-UP: Mains Disturbances; Front View

