



PHOTOS - TEST SETUP


Company: Itron

Product Name: ERG-7600-005


Report No.: ITRO67 – Test Setup Photos

1. Test Setup Photographs


1.1.1. Test Setup




Digital Emissions ERG-7600-005, 1-18GHz Back




ERG-7600-005, 30MHz-1GHz Back



ERG-7600-005, 30MHz-1GHz Front




Spurious Emissions ERG-7600-005 1-18GHz Back




Spurious Emissions ERG-7600-005, 1-18GHz Front

1.1.2. Test Setup - RF#2 - Conducted



RF Conducted Test Setup 1



RF Conducted Test Setup 2

ERG-7600-005 deemed by Itron to be the worst case and covers the following models also. Please see Declaration of Similarity in reports:

ERG-7600-006
ERG-7600-010



575 Boulder Court
Pleasanton, California 94566, USA
Tel: +1 (925) 462 0304
Fax: +1 (925) 462 0306
www.micomlabs.com