

Photo # 3

Unit Partially Disassembled (SCORPIUS 980)




Photo # 4

Unit Partially Disassembled (SCORPIUS 980)



Photo # 5

Unit Partially Disassembled (SCORPIUS 980)

98E1255




Photo # 6

Unit Partially Disassembled (SCORPIUS 980)

98E1255




Photo # 7

Unit Partially Disassembled (SCORPIUS 980)

98E1255




Photo # 10

Unit Partially Disassembled (SCORPIUS 980N plus)






Photo # 12

Unit Partially Disassembled (SCORPIUS 980N plus)



Photo # 13

Unit Partially Disassembled (SCORPIUS 980N plus)

98E1255




Photo # 14

Unit Partially Disassembled (SCORPIUS 980N plus)

98E1255

