

1.2 Conducted Emission Test Setup Photos




Photo 1.2-1 – Conducted Emission Test Setup [Front View]



Photo 1.2-2 – Conducted Emission Test Setup [Front View]

TÜV SÜD America Inc
141 14th Street NW
New Brighton, MN 55112

Phone: 651-631-2487
www.tuv-sud-america.com

1.3 Radiated Magnetic Emissions – Operation within the band 13.110-14.010 MHz



Photo 1.3-1 – Front View of the Test Setup, 3m - Operation within the band 13.110-14.010 MHz



Photo 1.3-2 – Back View of the Test Setup, 3m - Operation within the band 13.110-14.010 MHz

1.4 Occupied Bandwidth



Photo 1.4-1 – Occupied Bandwidth

1.5 Radiated Emissions – Out of Band Emission



Photo 1.5-1 – Front View of the Test Setup, 3m - Out of band emissions below 30MHz



Photo 1.5-2 – Back View of the Test Setup, 3m - Out of band emissions below 30MHz



Photo 1.5-3 – Front View of the Test Setup, 3m - Out of band emissions 30 - 1000MHz




Photo 1.5-4 – Back View of the Test Setup, 3m - Out of band emissions 30 - 1000MHz

1.6 Frequency Stability Test Photo



Photo 1.6-1 – Frequency stability Test Setup