



APPENDIX 3: Photographs of test setup

Conducted Emission




Radiated Spurious Emission


Front



Rear
below 1 GHz




above 1 GHz




Pre-check of Worst Case Position


X-axis



Y-axis



Z-axis



End of Report