

EXHIBIT 2: Equipment Photographs

Equipment Photographs

The following pages contain photographs of the tested sample as provided by ADTRAN, Inc. ADTRAN, Inc. respectfully requests that these photographs be withheld from public inspection.

List of Included Photographs:

Photograph 2.1	MPS: Front / Top View
Photograph 2.2	MPS: Rear / Bottom View
Photograph 2.3	MPS: T1 Interface Card – Component Side
Photograph 2.4	MPS: T1 Interface Card – Solder Side
Photograph 2.5	MPS: Inside Chassis
Photograph 2.6	MPS: Main PCB – Component Side
Photograph 2.7	MPS: Main PCB – Solder Side
Photograph 2.8	MPS: Inside Chassis – Boards Removed

A



Photograph 2.1
Tracer Monitored Protection Switch
Front / Top View


ADTRAN, Inc.
M/N: 1280300L1
FCC ID: HDCTRACERL9

A




Photograph 2.2
Tracer Monitored Protection Switch
Rear / Bottom View

ADTRAN, Inc.
M/N: 1280300L1
FCC ID: HDCTRACERL9



Photograph 2.3
Tracer Monitored Protection Switch
T1 Interface Card – Component Side

A




Photograph 2.4
Tracer Monitored Protection Switch
T1 Interface Card – Solder Side




Photograph 2.5
Tracer Monitored Protection Switch
Inside Chassis

A




Photograph 2.6
Tracer Monitored Protection Switch
Main PCB – Component Side

A



Photograph 2.7
Tracer Monitored Protection Switch
Main PCB – Solder Side

A



Photograph 2.8
Tracer Monitored Protection Switch
Inside Chassis – Boards Removed