


8- This equipment is below the low threshold for SAR evaluation under general public exposures conditions at distances greater than 2.5 cm.

All testing has been performed by NEMKO Canada. If other information is required, please refer to test report from NEMKO Canada.

Dated 22 Day of September 20 06
this _____

By:  _____
Signature Printed

Title: Project Manager (R&D)

On behalf of : DAP Technologies

Telephone: 418-681-7835 #395