



APPENDIX 3: Photographs of test setup

Radiated Spurious Emission

Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report