






KUSTOM SIGNALS, INC.
EXHIBIT 2.983(d) (7)

NOTES:
1. ALL TANT CAPS ARE 10% UNLESS NOTED OTHERWISE.
2. IF 10K STATIC RESISTOR NOT REMOVED, TEST IF RESISTOR R7 SHOULD BE REMOVED (8M).



REVISIONS			
REV	ECO	DATE	BY
0	REL	11-08	MAA

EFFECTIVE WORKBOOK REV. = 0			
REV	ECO	DATE	BY
0	REL	11-08	MAA

TITLE			
REV	ECO	DATE	BY
0	REL	11-08	MAA

MOTHERBOARD			
REV	ECO	DATE	BY
0	REL	11-08	MAA

SCHEMATIC: TALON			
REV	ECO	DATE	BY
0	REL	11-08	MAA

UNIT			
REV	ECO	DATE	BY
0	REL	11-08	MAA

RADAR			
REV	ECO	DATE	BY
0	REL	11-08	MAA

SHEET			
REV	ECO	DATE	BY
0	REL	11-08	MAA

