

APPENDIX 3: Photographs of test setup

Transmitter unwanted emissions in the spurious domain




Photo 1



Photo 2

Worst Case Position

Test Range	Frequency	Horizontal	Vertical
Below 1 GHz	470.125 MHz 539.000 MHz 607.875 MHz	Z-axis	Y-axis
Above 1 GHz	470.125 MHz 539.000 MHz	Z-axis	X-axis
	607.875 MHz	Z-axis	Z-axis

X-axis



Y-axis



Z-axis



Antenna Terminals Conducted




Photo 1

End of Report