

Attachment I
First Article Inspection Results
Lanyard Pin Assembly

INSPECTION REPORT (SIDE A)

FIRST ARTICLE YES ☒ NO

(Ref. Work Instructions FTL.QUA.310-02 and FTL.QUA.430-10)

Page 1 of 1

Program or Project: SPD-101 Work Order: _____

Contract No:

Part or Assy. Name: LANYARD PIN


Part No:

Serial Number(s): 11/A Quantity Inspected:

Revision Level:

[illegible]

Notes:



-001

INTERFACE CONTROL DRAWING	
UNLESS OTHERWISE SPECIFIED	
DIMENSIONS ARE IN INCHES	
TOLERANCES ON	
1. PLACE	±.010
2. PLACE	±.010
3. PLACE	±.010
4. PLACE	±.010
FRACTIONS 1/8	
ANGLES ±1°	
DATE	1968 DEC
BY	55827 P3-03-0042
SCALE	1/1" = 1/4" SHEET 1 OF 1
TITLE LANYARD, PIN SRR-406	
8830 NW 18TH TERRACE, FT LAUDERDALE, FL 33309	