

Annex C

Test setup photographs

part of / in addition to

Test report no.: 25010978-44359-0

Table of contents


1. Conducted measurement	3
2. Radiated measurements ($1\text{ MHz} < f < 1000\text{ MHz}$)	4

Annex C of TR no.: 25010978-44359-0

1. Conducted measurement




Photograph 1: Overall view, with spectrum analyzer and power meter.



Photograph 2: Close view, with oscilloscope.


2. Radiated measurements ($1 \text{ MHz} < f < 1000 \text{ MHz}$)



Photograph 3: Overall view 1. Radiated cabinet measurement with signal power on EUT 2 kW. The door of the chamber is closed. The power supply is provided through the socket in the turn table.



Photograph 4: Overall view 2. Radiated cabinet measurement with signal power on EUT 2 kW. The door of the chamber is closed. The power supply is provided through the socket in the turn table.



Photograph 5: Overall view. Radiated cabinet measurement with signal power on EUT 5 kW. The door of the chamber is open to get the power supply cable in the chamber.



Photograph 6: Overall view. Power supply cable going through the door in the chamber.