


Appendix L: Test Photographs



Photograph 2: Radiated Emissions Testing – Front View (< 1 GHz)



Photograph 3: Radiated Emissions Testing – Back View (< 1 GHz)



Photograph 4: Radiated Emissions Testing – Front View (> 1 GHz)



Photograph 5: Radiated Emissions Testing – Back View (> 1 GHz)

Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Client: Hunter Engineering Co.
Model/HVIN: 45-1549
Standards: FCC 15.247
IDs: LS3-45-1549/2938A-451549
Report #: 2016038DXT



Photograph 6: Conducted Emissions Testing – Front View

Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Client: Hunter Engineering Co.
Model/HVIN: 45-1549
Standards: FCC 15.247
IDs: LS3-45-1549/2938A-451549
Report #: 2016038DXT



Photograph 7: Conducted Emissions Testing – Back View