

EXHIBIT 4



Block Diagram and Schematic

Para. 2.1033(b)(5)




Retlif Testing Laboratories

Test Report No. R-7170
FCC ID: MIKNUMETNC97A





NOTE: ALL PARTS SHOULD BE PLACED AS CLOSE TO PINS AS POSSIBLE.
* CAPACITORS ARE IN PICO FARADS




1001 SHOULD BE PLACED AS CLOSE TO J2 AS POSSIBLE
CAPACITORS 1206

NU-METRICS	
University Drive	
Box 516	
Uniontown, PA 15401	
Title	NC-97
Size	Document Number
Date	April 1, 1998 Sheet 1 of 1
REV	E







NOTE: