

APPENDIX 3: Photographs of test setup

Conducted Emission



Front



Side

Radiated Spurious Emission


ANT 2
Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)




Radiated Spurious Emission


ANT 3
Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)




Pre-check of Worst Case Position

Module
X-axis



Y-axis




Z-axis




Pre-check of Worst Case Position

Antenna

**ANT 2
X-axis**




**ANT 3
X-axis**



Y-axis




Y-axis



Z-axis



Z-axis




Pre-check of Worst Case Position

ANT 2

Without Tag




With Tag



ANT 3

Without Tag



With Tag



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report