

6 Photographs of the Test Set-Up


Photograph 1: Set-up for Conducted Emission on AC Mains



Prüfbericht - Nr.: 16007536 001
Test Report No.:

Seite 14 von 15
Page 14 of 15

Photograph 2: Set-up for Radiation Measurement Below 1GHz



Photograph 3: Set-up for Radiation Measurement Above 1GHz

