



### **APPENDIX 3: Photographs of test setup**

#### **Radiated Spurious Emission**



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124


**Worst Case Position (Horizontal: X-axis/ Vertical:X-axis)**

**Module**


**X-axis**



**Y-axis**



**Z-axis**




**Worst Case Position**  
**(Horizontal: X-axis/ Vertical:X-axis below 1GHz)**  
**(Horizontal: X-axis/ Vertical:Y-axis above 1GHz)**

**Ant  
X-axis**



**Y-axis**



**Z-axis**



**End of Report**