

APPENDIX 3: Photographs of Test Setup

Radiated Spurious Emission




Photo 1




Photo 2


Worst Case Position

		Module	Antenna
Below 1 GHz	Horizontal	X	X
	Vertical	X	X
Above 1 GHz	Horizontal	Z	Z
	Vertical	Y	Y

Module
X-axis




Antenna
X-axis



Y-axis




Y-axis



Z-axis



Z-axis



Antenna Terminal Conducted Tests



Photo 1

End of Report