


Prüfbericht - Nr.:
Test Report No.

14011032 001

Seite 1 von 1
Page 1 of 1



Ref -10 dBm *Att 0 dB RBW 3 kHz Marker 1 [T1]
VBW 10 kHz -28.13 dBm
SWT 15 ms 49.860200000 MHz



Date: 5.JAN.2006 16:33:39

LP

93045