18. EUT SETUP PHOTOS



Radiated Emission Setup Photos (Worst Emission Position)



Conducted Emission Setup Photos (Worst Emission Position)

COMPLIANCE CONSULTING SERVICES DOCUMENT NO:CCSUP4002B2

1366 BORDEAUX DRIVE SUNNYVALE, CA 94089 USA TEL:(408) 752-8166 FAX:(408) 752-8168

This report shall not be reproduced except in full, without the written approval of CCS.