




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz 1.43 dBm
SWT 5 ms 2.411800000 GHz

Ref 10 dBm

*Att 20 dB

SWT 5 ms

2.411800000 GHz



Comment A: RF conducted spurious at low channel
ATT=3dB CL=1dB


Date: 14.AUG.2002 17:46:10



*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz -44.58 dBm
SWT 240 ms 674.64000000 MHz

Ref 0 dBm

*Att 10 dB



Comment A: RF conducted spurious at low channel
ATT=3dB CL=1dB

Date: 14.AUG.2002 17:53:04




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz -59.72 dBm
SWT 760 ms 2.513566000 GHz

Ref 0 dBm

*Att 10 dB

1 PK
MAXH



Start 2.4835 GHz

751.65 MHz/

Stop 10 GHz

Comment A: RF conducted spurious at low channel

ATT=3dB CL=1dB

Date: 14.AUG.2002 17:54:05




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz -57.81 dBm
SWT 1.5 s 24.850000000 GHz

Ref 0 dBm

*Att 10 dB

1 PK
MAXH



Start 10 GHz

1.5 GHz/

Stop 25 GHz

Comment A: RF conducted spurious at low channel

ATT=3dB CL=1dB

Date: 14.AUG.2002 17:55:22




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz 1.14 dBm
SWT 5 ms 2.436800000 GHz

Ref 10 dBm


*Att 20 dB

SWT 5 ms

2.436800000 GHz



Comment A: RF conducted spurious at middle channel{
ATT=3dB CL=1dB
Date: 14.AUG.2002 17:58:29




Comment A: RF conducted spurious at middle channelre@
ATT=3dB CL=1dB
Date: 14.AUG.2002 18:00:07



*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz -60.94 dBm
SWT 760 ms 2.543632000 GHz

Ref 0 dBm

*Att 10 dB



Comment A: RF conducted spurious at middle channel{
ATT=3dB CL=1dB

Date: 14.AUG.2002 18:01:05




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz -57.28 dBm
SWT 1.5 s 24.61000000 GHz

Ref 0 dBm

*Att 10 dB

1 PK
MAXH



Start 10 GHz

1.5 GHz/

Stop 25 GHz

Comment A: RF conducted spurious at middle channel{
ATT=3dB CL=1dB

Date: 14.AUG.2002 18:02:46




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz 0.38 dBm
SWT 5 ms 2.461800000 GHz

Ref 10 dBm

*Att 20 dB


SWT 5 ms

2.461800000 GHz



Comment A: RF conducted spurious at high channel
ATT=3dB CL=1dB

Date: 14.AUG.2002 18:35:22



Comment A: RF conducted spurious at high channel

ATT=3dB CL=1dB

Date: 14.AUG.2002 18:37:04




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz -48.64 dBm
SWT 760 ms 2.483500000 GHz

Ref 0 dBm

*Att 10 dB

1 PK
MAXH



Start 2.4835 GHz

751.65 MHz/

Stop 10 GHz

Comment A: RF conducted spurious at high channel J{

ATT=3dB CL=1dB


Date: 14.AUG.2002 18:38:47



*RBW 100 kHz Marker 1 {T1}
VBW 300 kHz -57.39 dBm
SWT 1.5 s 24.790000000 GHz

Ref 0 dBm

*Att 10 dB



Comment A: RF conducted spurious at high channel J{

ATT=3dB CL=1dB

Date: 14.AUG.2002 18:40:28