

Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA20170
<http://www.rheintech.com>

Client: Harris Corporation
EUT: XG-15P 700/800 MHz
ID's: OWDTR-0134-E/3636B-0134
Standards: FCC Part 90
Report #: 2015011

Appendix P: Internal Photographs

Photograph 10: Inside Front Cover



Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA20170
<http://www.rheintech.com>

Client: Harris Corporation
EUT: XG-15P 700/800 MHz
ID's: OWDTR-0134-E/3636B-0134
Standards: FCC Part 90
Report #: 2015011

Photograph 11: **Inside Rear Cover**



Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA20170
<http://www.rheintech.com>

Client: Harris Corporation
EUT: XG-15P 700/800 MHz
ID's: OWDTR-0134-E/3636B-0134
Standards: FCC Part 90
Report #: 2015011


Photograph 12: **Interface PWB in Unit**



Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA20170
<http://www.rheintech.com>

Client: Harris Corporation
EUT: XG-15P 700/800 MHz
ID's: OWDTR-0134-E/3636B-0134
Standards: FCC Part 90
Report #: 2015011


Photograph 13: Interface PWB Component Side



Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA20170
<http://www.rheintech.com>

Client: Harris Corporation
EUT: XG-15P 700/800 MHz
ID's: OWDTR-0134-E/3636B-0134
Standards: FCC Part 90
Report #: 2015011

Photograph 14: Interface PWB LCD Side




Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA20170
<http://www.rheintech.com>

Client: Harris Corporation
EUT: XG-15P 700/800 MHz
ID's: OWDTR-0134-E/3636B-0134
Standards: FCC Part 90
Report #: 2015011

Photograph 15: Main PWB in Unit



Photograph 16: Main PWB Side 1



Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA20170
<http://www.rheintech.com>

Client: Harris Corporation
EUT: XG-15P 700/800 MHz
ID's: OWDTR-0134-E/3636B-0134
Standards: FCC Part 90
Report #: 2015011

Photograph 17: Main PWB Side 2

