

Appendix A: Test Configuration Photographs

Photograph 1: Radiated Emissions – Front View (Below 1 GHz)



Photograph 2: Radiated Emissions – Back View (Below 1 GHz)



Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Client: L3Harris Technologies
Model: XL-85M UHF-L
ID's: OWDTR-0177-E/3636B-0177
Standards: FCC §90,80,74,22/ISED RSS-119
Report #: 2024073TNB

Photograph 3: Radiated Emissions – Front View (Above 1 GHz)



Photograph 4: Radiated Emissions – Back View (Above 1 GHz)



Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Client: L3Harris Technologies
Model: XL-85M UHF-L
ID's: OWDTR-0177-E/3636B-0177
Standards: FCC §90,80,74,22/ISED RSS-119
Report #: 2024073TNB

Photograph 5: Conducted Emissions - Front View



Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Client: L3Harris Technologies
Model: XL-85M UHF-L
ID's: OWDTR-0177-E/3636B-0177
Standards: FCC §90,80,74,22/ISED RSS-119
Report #: 2024073TNB

Photograph 6: Conducted Emissions - Rear View



Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Client: L3Harris Technologies
Model: XL-85M UHF-L
ID's: OWDTR-0177-E/3636B-0177
Standards: FCC §90,80,74,22/ISED RSS-119
Report #: 2024073TNB

Photograph 7: Conducted Antenna Port Spurious Emissions



Photograph 8: Transient Frequency Behavior

