

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
P2SR900CE
4171B-R900CE
23-0195
October 17, 2023
Neptune Technology Group Inc.
R900

INTERNAL PHOTOGRAPHS



Figure 1. EUT, Cover Removed and Empty

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
P2SR900CE
4171B-R900CE
23-0195
October 17, 2023
Neptune Technology Group Inc.
R900



Figure 2. Main Board, Installed

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
P2SR900CE
4171B-R900CE
23-0195
October 17, 2023
Neptune Technology Group Inc.
R900




Figure 3. Enclosure, Electronics Removed

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
P2SR900CE
4171B-R900CE
23-0195
October 17, 2023
Neptune Technology Group Inc.
R900




Figure 4. Main Board, Top, With Shield

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
P2SR900CE
4171B-R900CE
23-0195
October 17, 2023
Neptune Technology Group Inc.
R900




Figure 5. Main Board, Top, Shield Removed