

Report No.: 0215486
Model No.: #08983Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement

hp

MKR 33.187 msec

REF 107.0 dB μ V

AT 10 dB


.00 dB

PEAK

LOG

10

dB/

VA SB
SC FC
CORRTested By: [Signature]Date: 2-11-02Checked By: [Signature]Date: 11/11Test Result : Pass / Fail (NA)

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 75.0 msec

Report No.: 0215486
Model No.: #08983

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement


hp

REF 107.0 dBμV

AT 10 dB

MKR 33.200 msec

.00 dB



Tested By: *[Signature]*
(Francis)

Date: 7-11-02

Checked By: *[Signature]*
(Vah)

Date: 11/11

Test Result : Pass / Fail / NA

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz


#VBW 3 MHz

#SWP 40.0 msec

Report No.: 0215486
Model No.: #08983

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement

hp
REF 107.0 dBμV AT 10 dB MKR 1.2000 msec
-1.09 dB



Tested By: [Signature]
(Cargi)
Date: 7-11-02
Checked By: [Signature]
(Ivan)
Date: 11/11
Test Result : Pass / Fail / NA

CENTER 27.146 MHz SPAN 0 Hz
#RES BW 3.0 MHz #VBW 3 MHz #SWP 40.0 msec

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement

Report No.: 0215486
Model No.: #08993

MKR 400.00 μ sec

REF 107.0 dB μ V

AT 10 dB


-1.09 dB

PEAK

LOG

10

dB/



VA SB
SC FC
CORR

Tested By :

(*Trang Vi*)

Date : 7-11-02

Checked By :

(*Tran*)

Date : _____

Test Result : Pass / Fail / NA

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 40.0 msec