



Photos

***Radio frequency interference from Fingerprint Reader
Precise 100AX according to FCC requirements***

Performed for Precise Biometrics AB

Page 1 of 4

This exhibit is an extract of

DELTA Test Report E501178-1
DANAK-196991
11 June 2003

containing only the photos of the test set-ups.

DELTA

Danish Electronics,
Light & Acoustics

Venlighedsvej 4
2970 Hørsholm
Denmark

Tel. (+45) 72 19 40 00
Fax (+45) 72 19 40 01
www.delta.dk





Photo A2.1 AC mains conducted emission measurement.



Photo A2.2 AC mains conducted emission measurement.



Photo A2.3 AC mains conducted emission measurement.



Photo A3.1 Radiated electromagnetic field measurement.



Photo A3.2 Radiated electromagnetic field measurement.



Photo A3.3 Radiated electromagnetic field measurement.