


Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 90, RSS-119	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (Radiated Emissions)



Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 90, RSS-119	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (Radiated Emissions)




Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 90, RSS-119	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (Radiated Emissions)



Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 90, RSS-119	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (Radiated Emissions - EUT Flat)




Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 90, RSS-119	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (Radiated Emissions - EUT Side)




Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 90, RSS-119	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (Radiated Emissions - EUT Upright)




Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 90, RSS-119	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (RF conducted measurements)



Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 90, RSS-119	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (RF conducted measurements)




Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 90, RSS-119	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (RF conducted measurement - Frequency Stability)



Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 90, RSS-119	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (RF conducted measurement - Transient Frequency Behavior)



Client:	Xetawave LLC	Job Number:	JD103500
Model:	Xeta1	T-Log Number:	T103571
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 90, RSS-119	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (RF conducted measurement - Transient Frequency Behavior)

