

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission



Photo 1



Photo 2

Worst Case Position

Test Range	Horizontal	Vertical
Below 1 GHz	Z-axis	Y-axis
Above 1 GHz	Y-axis	Y-axis

X-axis



With Tag



Y-axis



Without Tag (Worst)



Z-axis



Antenna Terminal Conducted Tests




Photo 1



Photo 2

End of Report