



### **APPENDIX 3: Photographs of Test Setup**

#### **Radiated Spurious Emission (WLAN)**




**Photo 1**




**Photo 2**

**Radiated Spurious Emission**  
**(BT LE)**



**Photo 1**



**Photo 2**

**Worst Case Position**  
**(WLAN)**

| Test Range  | Horizontal | Vertical |
|-------------|------------|----------|
| Below 1 GHz | Y-axis     | Z-axis   |
| Above 1 GHz | Y-axis     | Z-axis   |

**X-axis**



**Y-axis**



**Z-axis**



**Worst Case Position**  
**(BT LE)**

| Test Range  | Horizontal | Vertical |
|-------------|------------|----------|
| Below 1 GHz | X-axis     | X-axis   |
| Above 1 GHz | Y-axis     | Z-axis   |

**X-axis**



**Y-axis**



**Z-axis**



### Antenna Terminal Conducted Tests (WLAN)




Photo 1



Photo 2

**Antenna Terminal Conducted Tests**  
**(BT LE)**



**Photo 1**



**Photo 2**

**End of Report**