

Company: Radwin

Product Name: AP0158770

Report No.: RDWN48 – Test Setup Photos

PHOTOS - TEST SETUP




1. Test Setup Photographs

1.1.1. Test Setup - DFS - Conducted - DFS - Conducted




AP0158770 Conducted DFS Setup


1.1.2. Test Setup - RE#1 - Radiated Emissions - 3m Chamber




Radiated Emissions Antenna RW-9061-5002



Radiated Emissions Antenna RW-9401-5002



Radiated Emissions Antenna RW-9613-4960



Radiated Emissions Antenna RW-9732-4958

1.1.3. Test Setup - RF#2 - Conducted



RF Conducted



575 Boulder Court
Pleasanton, California 94566, USA
Tel: +1 (925) 462 0304
Fax: +1 (925) 462 0306
www.micomlabs.com