


Prüfbericht - Nr.:
Test Report No.

14004841 001

Seite 3 von 4
Page 3 of 4

1.2 Internal view

1.2.1 Front side 1



The yellow circle indicates the location of the antenna.

Prüfbericht - Nr.:
Test Report No.

14004841 001

Seite 4 von 4
Page 4 of 4

1.2.2 Rear side 1



1.2.3 Rear side 2

