


*Att 30 dB

VBW 300 kHz

119.15 dB μ V

SWT 2.5 ms

2.401808000 GHz



200 kHz/

Span 2 MHz

ATT=3dB CL=1dB

Date: 17.JUN.2002 15:01:13




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz 66.63 dBuV
SWT 240 ms 665.160000000 MHz

Ref 117 dBuV

*Att 20 dB

1 PK
MAXH



Start 30 MHz

237 MHz/

Stop 2.4 GHz

Comment A: RF conducted spurious at low channel
ATT=3dB CL=1dB

Date: 17.JUN.2002 15:03:25




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz 66.82 dBuV
SWT 760 ms 2.483500000 GHz

Ref 107 dBuV

*Att 10 dB

1 PK
MAXH



Comment A: RE conducted spurious at low channel
ATT=3dB CL=1dB

Date: 17.JUN.2002 15:05:40



*RBW 100 kHz Marker 1 [T1]

VBW 300 kHz

49.50 dBuV


Ref 107 dBuV

*Att 10 dB

SWT 1.5 s

24.940000000 GHz

1 PK
MAXH



Comment A: RF conducted spurious at low channel

ATT=3dB CL=1dB

Date: 17.JUN.2002 15:07:41




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz 119.27 dBμV
SWT 2.5 ms 2.440812000 GHz

Ref 127 dBμV

*Att 30 dB

1 PK
MAXH



Center 2.441 GHz

200 kHz/

Span 2 MHz

Comment A: RF conducted spurious at middle channel

ATT=3dB CL=1dB

Date: 17.JUN.2002 15:09:37




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz 66.85 dBμV
SWT 240 ms 703.080000000 MHz

Ref 117 dBμV

*Att 20 dB

1 PK
MAXH



Start 30 MHz

237 MHz/

Stop 2.4 GHz

Comment A: RF conducted spurious at middle channel

ATT=3dB CL=1dB

Date: 17.JUN.2002 15:11:37




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz 66.50 dBμV
SWT 760 ms 2.528599000 GHz

Ref 107 dBμV

*Att 10 dB

1 PK
MAXH



Comment A: RF conducted spurious at middle channel

ATT=3dB CL=1dB

Date: 17.JUN.2002 15:12:54




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz 51.37 dBμV
SWT 1.5 s 24.790000000 GHz

Ref 107 dBμV

*Att 10 dB

1 PK
MAXH



Comment A: RF conducted spurious at middle channel

ATT=3dB CL=1dB

Date: 17.JUN.2002 15:15:29




*RBW 100 kHz Marker 1 [T1]
VEW 300 kHz 119.36 dBuV
SWT 2.5 ms 2.479808000 GHz

Ref 127 dBuV

*Att 30 dB

1 PK
MAXH



Comment A: RF conducted spurious at high channel
ATT=3dB CL=1dB

Date: 17.JUN.2002 15:17:47



*RBW 100 kHz Marker 1 [T1]

VBW 300 kHz 66.84 dBuV


Ref 117 dBuV

*Att 20 dB

SWT 240 ms

741.000000000 MHz

1 PK
MAXH



Start 30 MHz

237 MHz/

Stop 2.4 GHz

Comment A: RF conducted spurious at high channel

ATT=3dB CL=1dB

Date: 17.JUN.2002 15:20:59




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz 69.30 dBµV
SWT 760 ms 2.483500000 GHz

Ref 110 dBµV

*Att 20 dB

1 FK
MAXH



Comment A: RF conducted spurious at high channel

ATT=3dB CL=1dB

Date: 17.JUN.2002 15:23:01




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz 50.19 dBμV
SWT 1.5 s 24.580000000 GHz

Ref 107 dBμV

*Att 10 dB

1 FK
MAXH



Comment A: RF conducted spurious at high channel

ATT=3dB CL=1dB

Date: 17.JUN.2002 15:25:21