





Prüfbericht - Nr.: 16002795 001
Test Report No.:

Seite 14 von 17
Page 14 of 17

6 Photographs of the Test Set-Up

Photograph 1: Set-up for Conducted Emission on AC Mains



Prüfbericht - Nr.: 16002795 001
*Test Report No.:***Seite 15 von 17**
*Page 15 of 17***Photograph 2: Set-up for Radiation Measurement Below 1GHz**

Prüfbericht - Nr.: 16002795 001
Test Report No.:

Seite 16 von 17
Page 16 of 17

Photograph 3: Set-up for Radiation Measurement Above 1GHz

