

Response to TCB Findings

1. Please specify the label material

The label material is metallized polyester.

2. Please explain why AC line conducted emissions test was not conducted on the device.

This device is powered by a pure DC supply (vehicle battery).

3. There seems to be a cable connection between the receiver and the transmitter in the radiated emissions test set-up photo. Please clarify the purpose of this direct connection in terms of functionality.

The cable you see is a service cable; it is used for the purpose of recharging the batteries of the transmitter and is not connected during normal operation