



APPENDIX 3: Photographs of test setup

Conducted Emission





Radiated Spurious Emission


Front




Rear (below 30 MHz)



Rear (30 MHz - 1 GHz)



Rear (above 1 GHz)




Precheck of worst case position


X-axis



Y-axis



Z-axis



End of Report