



PHOTOS - TEST SETUP

Company: Sonos Inc

Product Name: S23

Report No.: BLE FCC & IC Test Setup Photos

1. Test Setup Photographs

1.1.1. Test Setup - AC Conducted Emissions



AC Mains Conducted Front




AC Mains Conducted Side

1.1.2. Test Setup - RE#1 - Radiated Emissions - 3m Chamber



Digital Emissions 30-1000MHz



TX Spurious 1-18GHz



TX Spurious 9 KHz – 30 MHz

1.1.3. Test Setup - RF#1 - Conducted



RF Conducted



575 Boulder Court
Pleasanton, California 94566, USA
Tel: +1 (925) 462 0304
Fax: +1 (925) 462 0306
www.micomlabs.com