APPENDIX 3: Photographs of Test Setup

Radiated Spurious Emission



Photo 1



Photo 2

Worst Case Position

Test Range	Horizontal	Vertical
Below 1 GHz	X-axis	X-axis
Above 1 GHz	X-axis	Y-axis

X-axis

Y-axis

Z-axis



Antenna Terminal Conducted Tests



Photo 1

Photo 2

End of Report