







Photograph 1: Internal View of DUT Bottom Removed




Photograph 2: Internal View of DUT PCB Removed




Photograph 3: Top Metal Housing Showing Back of Metal Piece



Photograph 4: Top Metal Removed From Top Housing



Photograph 5: Top Metal Housing Showing Top Side of Metal Piece



Photograph 6: Bottom Fan Housing



**Photograph 7: Bottom Fan Housing w/ Fan Removed
(Showing Back of Fan)**