







Photograph 1: Bottom Cover of DUT Off




Photograph 2: Bottom Cover of DUT Off




Photograph 3: Cover of DUT Off




Photograph 4: Side of DUT




Photograph 5: Disassembled DUT




Photograph 6: Side of DUT




Photograph 7: Power Supply Board Removed




Photograph 8: Power Board PCB




Photograph 9: Power Board PCB




Photograph 10: Power Board PCB




Photograph 11: Power Board PCB



Photograph 12: Power Board PCB




Photograph 13: Power Board PCB




Photograph 14: Power Board PCB







Photograph 17: LED PCB



Photograph 18: LED PCB Disassembled




Photograph 19: LED PCB




Photograph 20: LED PCB



Photograph 21: LED PCB




Photograph 22: LED PCB




Photograph 23: LED PCB




Photograph 24: LED PCB




Photograph 25: LED PCB




Photograph 26: LED PCB




Photograph 27: Front of Main PCB w/Heat Sink




Photograph 28: Front of Main PCB Heat Sink Removed




Photograph 29: Front of Main PCB



Photograph 30: Front of Main PCB



Photograph 31: Front of Main PCB



Photograph 32: Front of Main PCB