




Fig.4 Photograph of the Left Hand Side Touch status




Fig.5 Photograph of the Left Hand Side Tilt status




Fig.6 Photograph of the Right Hand Side Touch status





Fig.7 Photograph of the Right Hand Side Tilt status




Fig.8 Photograph of the BodyWorn status

Note:

1. The Mobile Phone without headphone in GPRS Mode BodyWorn Status.

2. Photographs of the EUT



Fig.9 Front View



Fig.10 Back View

3. Photographs of the battery



Fig.11 Front view of battery



Fig.12 Back view of battery

4. Photograph of the charger



Fig.13 Charger