




*Photograph B-1: Test Site Photo – Washington Lab – Front View*



*Photograph B-2: Test Site Photo – Washington Lab – Rear View*



*Photograph B-3: Test Site Photo – 16116 Orchard Grove Road – Front View*




*Photograph B-4: Radiated Emissions Test – 16116 Orchard Grove Road - Meter View*



*Photograph B-5: Radiated Emissions Test – 12028 Coldstream Drive - Front View*



*Photograph B-6: Radiated Emissions Test – 12028 Coldstream Drive – Overhead Feeder Line View*



*Photograph B-7: Radiated Emissions Test – 12028 Coldstream Drive - Meter View*



*Photograph B-8: Radiated Emissions Test – 12109 Sheets Farm Road – Front View*



*Photograph B-9: Radiated Emissions Test – 12109 Sheets Farm Road – Meter View*



*Photograph B-10: Radiated Emissions Test – 17907 Coachmans Road – Front View*



*Photograph B-11: Radiated Emissions Test – 17907 Coachmans Road – Meter View*