Photograph B-1: Test Site Photo – CURRENT Technologies Potomac Test Area – TXF-1 – Exterior view

Photograph B-2: Test Site Photo – CURRENT Technologies Potomac Test Area – TXF-1 – Interior view

Photograph B-3: Test Site Photo – CURRENT Technologies Potomac Test Area – TXF-2 – Exterior view



Photograph B-4: Test Site Photo – CURRENT Technologies Potomac Test Area – TXF-2 – Interior view

Photograph B-5: Test Site Photo – CURRENT Technologies Urbana Test Area – TXF-U1 – Exterior view

Photograph B-6: Test Site Photo – CURRENT Technologies Urbana Test Area – TXF-U1 – Interior view

Photograph B-7: Test Site Photo – CURRENT Technologies Orchard Hills Test Area – PLB-A1 – Exterior view

Photograph B-8: Test Site Photo – CURRENT Technologies Orchard Hills Test Area – PLB-A1 – Interior view

Photograph B-9: Test Site Photo – CURRENT Technologies Orchard Hills Test Area – PLB-A2 – Exterior view



Photograph B-10: Test Site Photo – CURRENT Technologies Orchard Hills Test Area – PLB-A2 – Interior view

Photograph B-11: Test Site Photo – CURRENT Technologies Orchard Hills Test Area – PLB-A3 – Exterior view

Photograph B-12: Test Site Photo – CURRENT Technologies Orchard Hills Test Area – PLB-A3 – Interior view

Photograph B-13: Test Site Photo – Washington Lab – Front View

Photograph B-14: Test Site Photo – Washington Lab – Rear View