


Appendix A. TEST PHOTOS

1 Photographs of Conducted Emissions Test Configuration


FRONT VIEW



REAR VIEW




CLOSE VIEW




Ant 1 (1002302)



Ant 3 (1002303)




Ant 5 (1002304)




2 Photographs of Radiated Emissions Test Configuration


FRONT VIEW



REAR VIEW



CLOSE VIEW




CLOSE VIEW



Ant 1 (1002302)



Ant 3 (1002303)



Ant 5 (1002304)

