

## Appendix 2 Photodocumentation

Description: General view #1

Division:  
Industry & Energy

Department: FG

Test report reference:  
INE-AT/FG-19/101

Page: 1 of 10

Date: 01.02.2019



## Appendix 2 Photodocumentation

Description: General view #2

Division:  
Industry & Energy

Department: FG

Test report reference:  
INE-AT/FG-19/101

Page: 2 of 10

Date: 01.02.2019



## Appendix 2 Photodocumentation

Description: Battery compartment opened


Division:  
Industry & Energy

Department: FG

Test report reference:  
INE-AT/FG-19/101

Page: 3 of 10

Date: 01.02.2019



## Appendix 2 Photodocumentation

Description: Microphone detached

Division:  
Industry & Energy

Department: FG

Test report reference:  
INE-AT/FG-19/101

Page: 4 of 10

Date: 01.02.2019

