

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1

(above 1 GHz)



Photo 2




Photo 3

(below 1 GHz)




Photo 4

Pre-check of Worst Case Position


X-axis



Y-axis



Z-axis



End of Report