


APPENDIX 3: Photographs of test setup

Radiated Spurious Emission

Front



Rear (Below 1 GHz)




Rear (Above 1 GHz)



Pre-Check of Worst Case Position


Module Axis



X-axis



Y-axis




Z-axis

Antenna axis



X-axis



Y-axis

End of Report