

APPENDIX 3: Photographs of Test Setup

Conducted Emission



Photo 1




Photo 2


Radiated Spurious Emission

Unilateral Transmission

Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)




Simultaneous Transmission


Front



Rear (Below 1 GHz)




Rear (Above 1 GHz)




Pre-check of Worst Case Position

EUT

X-axis



Y-axis




Z-axis




Antenna


X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report