


APPENDIX 3: Photographs of Test Setup

Conducted Emission



Front




Side

Radiated Spurious Emission

Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)



Worst Case Position


X-axis



Top




Y-axis



Bottom



Z-axis



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report