

APPENDIX 3: Photographs of test setup

Conducted Emission

Front



Side



Radiated Spurious Emission


Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)



Worst Case Position


Module
X-axis




Antenna
X-axis



Y-axis




Y-axis



Z-axis




Z-axis




Worst Case Position

Without Tag



With Tag



Antenna Terminal Conducted Tests



Photo 1




Photo 2

End of Report